Certificate of Location of Government Corner

ID#: 610406 **Description:** 1/4 SEC COR 4 5 61 **Date Set:** 6/29/1995 **County:** Olmsted

Section: 04 **Township:** 106N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in line with main fences E-W-N and 1' south of CP
Post w/sign 2' east
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes, William A. Jones, Deputy Surveyor South on true line between sections 4 and 5 39.80 chs. Set post at quarter section corner made mound, trench pits, planted cherry seeds NE and SW.

11-25-1992 County Surveyor dug at fence corner and Gov't prorated position. Found post hole.

6-26-1995 County Surveyor set cast iron cap on telspar pipe in line of fence North and at Prorated Gov't measure used for CSAH 9 R/W Plats.

12-4-2008 County Surveyor found cast iron cap on telspar pipe up 0.3' in good condition.