Certificate of Location of Government Corner

ID#: 611004 **Description:** 1/4 SEC COR 10 15 61 **Date Set:** 11/6/95 **County:** Olmsted

Section: 10 **Township:** 106N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 2' SW of CP, in line with fence east and 1' west of N-S fence
Sign on CP 2' NE
This corner is located by GPS measurement

Corner History:

Gov't Notes: 39.95 set 1/4 sec post midway and on line made mound, trench, pits, and planted cherry seeds. Deposited handful of white flint.

7-20-1885 T. Hunter (Field Book #14) at B found remains of old fence post corner of old fence. (caption at B old stake set new one). Book A page 400 same survey B found in ground the remains of old stake in line of old fence running east and also in line of bulks left to mark lines between owners S-W-N Drove new stake not marked in its place.

11-6-1995 County Surveyor dug at location of 1983 trav nail. Found post stub (6" dia) top at 2-1/2' deep. The stub was 12" long running into clay. The clay line was at 3' deep. There seemed to be a mark running deeper at same location which could have been another post at same location. Set 6' long cast iron cap on telspar pipe at post stub location. Nailed sign on C.P. to fence N-E-S. The corner falls 1.8' SW of C.P. in line of main line fence east and 1' west of N-S fence.

4-18-2007 County Surveyor found cast iron cap on telspar pipe up 0.4' in good condition.