# Certificate of Location of Government Corner

**ID#:** 611106 **Description:** 1/4 SEC COR 10 11 61 **Date Set:** 4/24/2003 **County:** Olmsted

**Section:** 11 **Township:** 106N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

**Reference Ties:**

The corner falls 1' north of centerline of E-W twp road and 2' west of fence north
County Survey Disk in PP SE 79.99'
County Survey Disk in CP NNE 27.18'
Center 28" Burr Oak N 102'
This corner is located by GPS measurement

**Corner History:**

10-1853 Gov't Notes: Set post at quarter sec corner. BT's Burr Oak 15" S77-1/2°E 154 links. Burr Oak 8" S1/4°W 423 links.

10-4-1983 County Surveyor dug from T.N. (set in the centerline of the E-W road and in line fences N&S) for 4' south, 3-1/2' west, 5' east, and 7' north, by 3' deep to clay. Hard packed black dirt on clay and wheel tracks in clay. Road in cut to west so we were surprised to find and black at all. Did not find corner.

7-15-2002 County Surveyor visited corner and set two points to GPS.

4-24-2003 County Surveyor set cast iron cap on telspar pipe midway and on line between section corners.

10-15-2008 County Surveyor found cast iron cap on telspar pipe down 0.6' in good condition.