Certificate of Location of Government Corner

ID#: 611405 **Description:** SEC COR 14 15 22 23 61 **Date Set:** 5/14/1992 **County:** Olmsted

Section: 14 **Township:** 106N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

County Survey Disk in W side PP N 1.56'
County highway disk in W side PP NE 1.53'
County highway disk top of 1st fence post S of PP 13.36'
Sign on PP 1' north
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes, William A. Jones, Deputy Surveyor North between Sections 22 and 23 80.00 chs. Set post at corner to sections 14,15,22 and 23 Lone Bur Oak 8" S 4° 30' E 650 links Deposited stone 8"x6"x2" made mound trench and pits and planted cherry seeds NE and SW.

6-1857 John Fraser (page 44, No. 66) Used corner.

5-1881 Thomas Hunter, Deputy County Surveyor (page 369 No. 360) Found corner post sturdy, said by John Coffin to be where corner stood. Chained east 39.8 chs. to ¼ corner then 39.87½ chs. to section corner.

7-1902 William Fraser, County Surveyor (Book B, page 41) Stone between two posts as corner. Set stakes north and south to ¼ corners for fencing.

10-21-1991 County Surveyor probed around transmission pole now used as corner post to fences south and east. Found stone 4"x8"x19" down 6", with large end up, found 4"x6"x10" stone below first stone, with post mark north of stone.

5-14-92 County Surveyor set telspar pipe with cast iron cap at location of stones found 10-21-91.

1-15-1993 Mn/Dot found cast iron cap on telspar pipe and took RP's CND W side PP NE 1.53'. CND top of 1st fence post S of PP 13.36'

7-15-2002 County Surveyor found cast iron cap on telspar pipe in good condition.