Certificate of Location of Government Corner

ID#: 612004 **Description:** 1/4 SEC COR 20 29 61 **Date Set:** 4/30/2007 **County:** Olmsted

Section: 20 **Township:** 106N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 2½' south of centerline of E-W twp road, in line with fence north and 7' east of PP line south
County Survey Disk in W side PP N 79.59'
60d spike in E side 24" Burr Oak SE 133.4' (grown over)
This corner is located by GPS reference stations "Salisbury A & B"

Corner History:

9-1853 Gov't Notes, William A. Jones, Deputy Surveyor West on true line between sections 20 and 29. 40.00 chs. Set post at quarter section corner. Bur Oak 10" N30E 99 lks. Bur Oak 9" S40E 178 lks.

9-1892 Thomas Fraser (P. 497 No. 469) County Surveyor, could find no corners between S.E. Cor. Sec. 20 and S.W. Cor. Sec. 19. Measured 2 miles and set ¼ Cor. 20-29 midway and on line. Drove drag tooth as corner.

10-1927 E.C. Burns Winona Co. Surveyor surveyed NE quarter of section 29, set pipe at quarter corner 20, 29 and 33' south of corner.

7-3-1975 County Surveyor dug with backhoe and found recorded drag tooth 4' deep. Set C.I.M. over 3/4"x9" rod over drag tooth. Did not find Burns pipe.

3-22-2007 County Surveyor visited area and found nothing.

4-30-2007 County Surveyor visited area of corner and found tie in PP north and tie in 16" Burr Oak (now 24") SE. Did not find CIM after digging down 3 1/2' through new fill. Road has been regraded with 4+ feet of fill at corner location. Set 5' telspar pipe w/cast iron cap down 0.4' at computed position.