Certificate of Location of Government Corner

ID#: 612104 **Description:** 1/4 SEC COR 21 28 61 **Date Set:** 11/2/1979 **County:** Olmsted

Section: 21 **Township:** 106N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls ½' south of E-W fence
Post w/sign 1' north
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes, William A. Jones, Deputy Surveyor West on true line between sections 21 and 28. 40.02½ chs. Set post at quarter section corner. Made Mound, trench, and pits, and planted Cherry seeds N.E. and S.W. 80.05 chs. To section corner.

5-1891 Thomas Fraser (Book A, Page 447, No. 432), County Surveyor, states "This corner was completely gone and has been for 20 years. No track had been kept of it except fence running East and West. Set temporary stake on line of fence and midway between E (S.W. Cor 21) and G (S.E. Cor. 21) (40.01½ chs.). Set temporary stake on line of fence and Midway between E & G, as they were not particular about lines in South half of Section running East and West. Did not run G." He used this corner to set the Center 21 at intersecting ¼ lines and to set the 1/16th East midway (but not on line). Also see Old Field Bk. 7, Pages 83-88).

10-1979 County Surveyor dug at a point midway between the section corners and at the E-W fence. Found small stone and soft spot slightly West of this point which was possible corner location.

11-2-1979 County Surveyor set a Cast Iron Cap on a 4' long square pipe (telspar) as the corner midway between the section corners and just on the south side of the fence running East and West as in Thomas Fraser's Survey No. 432.

4-18-2007 County Surveyor found cast iron cap on telspar pipe down 0.2' in good condition.