Certificate of Location of Government Corner

ID#: 612604 **Description:** 1/4 SEC COR 26 35 61 **Date Set:** 7/22/2003 **County:** Olmsted

Section: 26 **Township:** 106N **Range:** 11W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CSAH 29 and 8 1/2' east of fence SW
County Survey Disk in N side PP #35-4 SW 40.54'
County Survey Disk in E side PP NW 38.38'
This corner is located by GPS reference stations "29 A & B"

Corner History:

Gov't Notes: Set 1/4 corner post M&L 40 chs. Made mound, pits, trench, and planted cherry seeds. Deposited stone 7"x6"x2".

6-1857 John Fellows (P.43 No.65) shows 1/4 post (see survey for breakdown of sec 26).

1943 county highway department C.A. Armstrong, chief of party Field bk 180 P.76-77 did not dig here as former road grading had cut several feet below natural ground into rock. P.4 sta. 70+47 indicaties 1/4 corner intended to be placed midway and line between section corners. P.14 Topog culvert in place ± 200' east which the centerline of travelled road ± 7.4' N of centerline road as run if centerline old roadway is any good then 1/4 cor location could be ± 7' N of present centerline Co. Rd #29. However, road and fences appear in Topog notes as not too straight.

?? county highway department Field book 181 P.25, X-sections indicate old centerline road about 2' lower than ground 20' south and about level or slightly above ground at 20' north. No x-section taken right at this 1/4 cor. location but was taken ± 15' east 79+68.

4-25-2003 County Surveyor set concrete nail at assumed location and set 2 points to GPS to determine location.

7-22-2003 County Surveyor set 1" square pipe w/cap at surface from computed GPS data in centerline of CR 29. CSD in North side of pp 35-4 40.54' SW and CSD in East side of pp (no #) 38.38' NW.

2-20-2009 County Surveyor found 1" square pipe w/busted cap at surface in good condition. Replaced cap.