Certificate of Location of Government Corner

ID#: 612806 **Description:** 1/4 SEC COR 28 29 61 **Date Set:** 5/5/1977 **County:** Olmsted

Section: 28 **Township:** 106N **Range:** 11W **Monument Description:** Cast Iron Monument

Reference Ties:

The monument is down 0.3'
The corner falls 0.5' south of I-90 R/W fence
Rod in circular concrete monument beside state guardpost NE 38.68'
Concrete nail in S side PP #40380 E 29.76'
PI Rod in west bound lane of I-90 S 126.67'
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes, William A. Jones, Deputy Surveyor North between sections 28 and 29. 40.00 chs. Set post at quarter section corner. Made mound, trench and pits, and planted Cherry seeds N.E. and S.W.

10-1927 E.C. Burns, Winona County Surveyor placed pipe for quarter corner.

11-1961 MHD found a 6"x12"x14" stone with a cross 1.0' deep.

5-3-1977 County Surveyor found a 3/4"x8" iron with a 4"x6"x12" boulder (no cross) along side in the fill of the old road.

5-5-1977 County Surveyor dug with the backhoe. Found a 1"x2' pipe driven in the old road 2½' deep, 1.5' North and .4' East of the M.H.D. corner (removed). Set a C.I.M. over the pipe. This corner is in the centerline of the old road North and 6' North of the North I-90 R/W fence.

CORRECTION OF A CORNER: The correct corner is 1.5' North and .4' East of the M.H.D. Iron (removed).

2-10-2011 County survey crew found cast iron cap on square pipe in good condition.