Certificate of Location of Government Corner

ID#: 613404 **Description:** S 1/4 SEC COR 34 61 **Date Set:** 11/23/1998 **County:** Olmsted

Section: 34 **Township:** 106N **Range:** 11W **Monument Description:** Cast Iron Monument

Reference Ties:

The monument is down 0.5'
The corner falls 3' north of centerline of E-W twp road and 1 1/2' east of center old fence ridge north
County Survey Disk in PP N 27.80'
Traverse pt. Olive (1' sq. pipe w/cap) WNW 192.64'
This corner is located by GPS reference stations "Olive & Pedersen"

Corner History:

1853 Gov't Notes Set post and drove charred stake for 1/4 corner. Built mound and trench.

4-1892 Thos Fraser (P.483 No.460) corner gone, set temp point M&L 40.03-1/4 (2642.14) which came about in line of fence running south. Used above corner to set center section 3 by inters lines, no meas, no bearings.

10-17&18-1979 County Surveyor dug here with the backhoe from the traverse nail east 5', west 3', north 7', south 6-1/2' by 2-1/2' deep to clay. We measured from S 33-34 to the S 1/4 corner 35 and T. Fraser's prorated location would have been 3.90 north and 1.25 east of the t.n. Conditions here were porr, the old road being very close to clay. We did find some charcoal in the clay 4.5 north and 1.0 E of the t.n. We could not prove this was a charred stake but it was concentrated in an area of about 4 or 5" diam (the gov't notes call for a charred stake at this corner). Someone had dug here previously, their dig centered about 2' west of our t.n. and extending S 4', north 5', and being 3' wide. The line of the fence north here is now difficult to determine and their dig could have been centered on it.

11-23-1998 County Surveyor set CIM over 5/8" iron at midway and line point between section corners as Thomas Fraser did in his 1892 survey.

3-5-2009 County survey crew found CIM down 0.5' in good condition.

2-14-2011 County survey crew found CIM in good condition