Certificate of Location of Government Corner

ID#: 613406 **Description:** 1/4 SEC COR 33 34 61 **Date Set:** 1/4/1983 **County:** Olmsted

Section: 34 **Township:** 106N **Range:** 11W **Monument Description:** 1" square pipe w/cap RLS #8952

Reference Ties:

The monument is at the surface
The corner falls 0.3' east of centerline of CSAH 10
Punch hole in top center N end 24" CMP NW 41.51'
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes, William A. Jones, Deputy Surveyor North between sections 33 and 34. 40.00 chs. Set post at corner to sections. Deposited charred stake. Made mound, trench and pits, and planted plum seeds N.E. & N.W.

9-1857 E.P. Bircher, Surveyor, and Thomas Hunter, Deputy, (old Road Book--C.R. 24) surveyed a N-S road between sections 33 and 34.

1935 county highway department (C.H.D. Book 83, Page 66) topography shows a fence running East at this location and a measure of 2610' North from the fence to the center of the E-W road at Section Corner 27, 28, 33, & 34.

10-25-1979 County Surveyor this corner comes in a deep fill in C.R. 10 and we did not dig. The County Surveyor set a C.I.M. over a 5/8" x 20" iron at the corner. The corner is set N-S in line with the old fence ridge running East. This location is also a very good average of the fences on the E-W ¼ lines of Section 33 and 34. The corner is set E-W at a location which holds the fence at the 1/16 West midway to the Center 33 and the fence at the 1/16 East midway to the Center 34. The location is also in the center line of C.R. 10. Measured North 2611.70 to Section Corner 27-28-33-34. (See certificate filed.)

1-4-1983 County Surveyor drilled down to C.I.M. through new concrete on C.R. 10 with jackhammer. Set a 1" square pipe w/cap over the C.I.M.

4-11-2007 County survey crew found 1" square pipe w/cap at surface in good condition.

2-8-2011 County survey crew found 1" square pipe with cap in good condition.