Certificate of Location of Government Corner

ID#: 620105 **Description:** SEC COR 1 2 11 12 62 **Date Set:** 9/18/1973 **County:** Olmsted

Section: 01 **Township:** 106N **Range:** 12W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 6' south of centerline of E-W twp road and 36' west of centerline of farm drive south
Concrete nail in SSE side PP #38172 ENE 145.0'
NW corner glazed brick house SE 139.4'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes. North between sections 11 and 12. 80.00 chs. Set section corner post. Red Oak 8 N46°E 75 lks. Red Oak 8 S22°E 30 lks. Red Oak 4 N82°W 21 lks. Made trench.

6-1874 Thomas Hunter (P. 247 No. 248), County Surveyor, found stone set adjacent land corners when original corner stood.

10-1877 T. Hunter (P. 281 No. 278) found stake set on top of the stone P.247.

9-18-1973 County Surveyor dug and found limestone 2.9' deep in road. Set C.I.M. over railroad spike over stone.

9-28-1992 County Surveyor found CIM 21" deep in E-W rd, the road was regraded a couple of years ago according to adjacent land owner. It seems to have moved north a little. Set CIM over CIM Centerline E-W twp rd North 6'. Centerline Farm drive South, East 36'.

6-13-2002 County Surveyor found CIM down 0.5' in good condition.

4-5-2007 County Surveyor found CIM down 0.5' in good condition.