Certificate of Location of Government Corner

ID#: 620204 **Description:** 1/4 SEC COR 2 11 62 **Date Set:** 8/29/2001 **County:** Olmsted

Section: 02 **Township:** 106N **Range:** 12W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CSAH 7 and 5' north of centerline of E-W twp road
County Survey Disk in PP #38179 SW 75.65'
County Survey Disk in PP #38178 SSE 53.86'
Traverse pt CR 7C W 97.73'
County Survey Disk in PP #159 NE 42.49'
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes William A. Jones, Deputy Surveyor West on true line between sections 2 and 11. 40.00 chs. Set post at quarter section corner. Deposited charred stake. Made mounds, trench, and pits and planted cherry seeds S.W. and N.E.

6-1867 H.E. Horton, Pg. 86 No. 132 shows 1/4 Cor. Meas. South 40.24 chs to center sec. 11

6-1874 Thomas Hunter (P. 247 No. 248), County Surveyor, found part of old stake. Set stone 4" x 4" x 19".

7-17-1975 County Surveyor dug with backhoe and found 4" x 4" x 19" recorded limestone 6' deep in Co. Rd. 7. Set C.I.M. over 5/8" x 40" iron over stone found. Put junk around stone.

1-28-1992 County Surveyor dug down 8" to CIM in CR #7 set 30d spike at surface.

5-15-2000 County Surveyor found CIM down 0.7' in good condition. Tied out corner for CSAH 7 construction.

12-11-2000 County Surveyor set survey marker nail down 0.2' from 2000 tie out.

8-29-2001 County Surveyor set a 1" square pipe w/cap at surface from 2000 tie out.

6-11-2002 County Surveyor found 1" square pipe w/cap at surface in good condition.

11-25-2003 Mn/DOT survey crew found monument in good condition.

8-23-2004 County Surveyor found 1" square pipe w/cap at surface in good condition.

3-7-2007 County Surveyor found 1" square pipe w/cap at surface in good condition.