Certificate of Location of Government Corner

ID#: 620505 **Description:** SEC COR 5 6 7 8 62 **Date Set:** 5/15/2002 **County:** Olmsted

Section: 05 **Township:** 106N **Range:** 12W **Monument Description:** Cast Iron Cap telspar pipe

Reference Ties:

The corner falls 1' north of centerline of E-W twp road and 1' west of centerline of CR 102
County Survey Disk in SE side PP #15904 SW 43.93'
This corner is located by GPS measurement

Corner History:

9-1853 Set by William Jones. 80.00 Set post at corner to sect 5,6,7, & 8 deposited handful of charcoal made mound trench and pits and planted cherry seeds NE & SW.

No known records. School District #45 has positive description of 10 rods 165' square.

8-24-1973 County Surveyor dug 8' x 10' to clay found post at SW school yard near 165' from center crossroads. Found nothing Road fill about 20" then 16" black soil and pioneer road. Dug and scraped carefully. Couldn't have missed any stake or stone. Set nothing. If anything ever in area covered would have still been there.

7-8-1982 County Surveyor dug with the backhoe from a point 2' North and 4' East of the t.n. set last year as follows: 2' W; 4' WNW; 5'N; 9'E by 4 1/2' deep to clay. Measured 163'± South to the SW CP of school grounds and 265'± East to the NE CP of school grounds.

5-15-2002 County Surveyor set 5' telspar pipe w/Cast Iron Cap down 0.3' at computed location used in Chesterwoods Park survey from 1985.

4-20-2009 County Surveyor found cast iron cap on telspar pipe down 0.4' in good condition.