Certificate of Location of Government Corner

ID#: 620609 **Description:** SEC CEN 6 62 **Date Set:** **County:** Olmsted

Section: 06 **Township:** 106N **Range:** 12W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.
Limestone

Reference Ties:

This corner is located by GPS measurement

Corner History:

5-17-1871 T. Hunter P. 184 No. 195 found stake in mound as center section 6 tested by running both 1/4 lines and proved corner correct. 1/16 West set stake 19.94' then 18.23' to W 1/4 6'. 1/16 East set stake M & L 20.05'. 1/16 North set stake 19.94' then 20.03 to N 1/4 6

7-30-1981 County Surveyor at 1/16 north dug to clay from traverse nail, south 3', East 2 1/2', North 1', and West 1' ±. Found only the base of the corner post which had rotted off and was lying on the ground. The post went down 3'±, Could find no stake mark. The post centered .4' South and .1' East of the traverse nail.

8-6-1981 County Surveyor dug and found 2" x 11" x 21" pointed limestone 2.5' West and .30' South of the traverse nail. Found possible stake mark under stone. Set the stone back and put a 5/8" rod on the West side of it. Found another possible stake mark 1.3' West and 1.0' South of the stone.

8-7-1981 County Surveyor at 1/16 west dug from a point 3' East of the traverse nail, East for 6' and 4' South by 2' deep to clay. Did not find anything.

11-10-2008 Roger Brand used computed location at intersecting quarter lines as center of section 6.

4-23-2012 County survey crew found 2"x11"x21" pointed limestone down 1.5 in good condition.