Certificate of Location of Government Corner

ID#: 621206 **Description:** 1/4 SEC COR 11 12 62 **Date Set:** 4/21/2009 **County:** Olmsted

Section: 12 **Township:** 106N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 6' north of north edge of field rock pile
Post w/sign 2' east
This corner is located by GPS reference stations "Brubaker A & B"

Corner History:

9-1853 Gov't Notes William A. Jones, Deputy Surveyor North between sections 11 and 12. 40.00 chs. Set post at 1/4 section corner. Deposited charred stake. Made mound, trench, and pits. Planted Cherry seeds SW and NE.

6-1875 Thomas Hunter, County Surveyor, (Book A Page 281 No. 278) found the original 1/4 post standing in mound at the corner of the fence. Used the corner to set the Center 12 at intersecting 1/4 lines and the 1/16th South midway (20.02 1/2 chs.) and on line. He also set the 1/16th South of the Center 12. (from cards: same date. Found stake in mound at fence corner. 1/16 south set stake with stone on N &L S sides M & L 20.00 1/2 for line east. 1/16th east set stake M & L 19.91 1/2 for line North. (Note) 1/16th south also had small stones on N & S side of stake.)

6-1867 H.E. Horton Pg. 86 No. 132 shows 1/4 corner Meas. West 39.89 chs. To Cen. Sec. 11

10-1877 Hunter (Book A Caption Page 281) used the corner to set the 1/16th East midway and on line.

9-1891 Thomas Fraser, County Surveyor, (Book A Page 454 No. 438) found the stake at this corner and found Hunter's corner at the 1/16th South. He doubled the line and measure (19.99&3/4 chs.) from 1/4 corner 11-12 over the 1//16th South to reset Sec. Corner 11-12-13-14 which was gone.

3-24-1972 County Surveyor measured north from Sec. Corner 11-12-13-14 (found by Kerr in 1965). Found the 1/16th fence running east at 1322.5' and the 1/4 line fence running west at 2640.3'.

7-17-1975 County Surveyor dug for the 1/16th South of 1/4 corner 11-12 but did not find anything. Measured east from the fence line north at 1/4 corner 11-12 to the fence at the 1/16th East and the fence at the Center 12 and found the measurements to agree closely with Hunter's Chained 1313.1 from fence post on E side of huge willow at 1/4 corner 11-12 East to fence at 1/16th. Found corner post rotted off. Dug and found brace. Set steel post in hole. Found this to be off 1/4 line in 1979. About 10.4'So. Line.

4-19-1979 County Surveyor dug at the 1/16th South of the Center 12 and found a stake hole. Also dug at the Center 12 but did not find anything. Dug at the 1/16th West of the Cente 12 and found only a loop of wire near the calculated position.

4-19-1979 County Surveyor set a 1/2" (thinwall) iron pipe as the corner in line with the fence north and the fence west (as determined in 1972 since this fence is now gone). TheN-S fence at the 1/16th East is midway to the Center 12 (computed at the intersection of the E-W 1/4 line with the line from the N. 1/4 corner 12 to the stake mark found at the 1/16th South of the Center 12). We could not dig for this corner since it falls on the East side of a huge (36" diam.) Willow tree.

4-5-2007 County Surveyor visited area and found large pile of stone over corner location.

4-21-2009 County Surveyor visited area and could not find 1/2" pipe. Found 1" pipe, possibly guard, bent on top of rock pile. Looked like area of the corner had been dug out. Set 6' telspar pipe w/Cast Iron Cap up 0.1' at computed position form GPS and traverse data. Set post w/sign.