Certificate of Location of Government Corner

ID#: 621704 **Description:** 1/4 SEC COR 17 20 62 **Date Set:** 4/10/2009 **County:** Olmsted

Section: 17 **Township:** 106N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1' south of centerline of E-W twp road and in line with fence north
Nail in large Burr Oak ESE 109.9' (grown over)
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes West on true line between sections 17 and 20 39.93 chs. Set quarter section post. Burr Oak 7 in. N40°E 31 lks. Burr Oak 10 in S56°W 37 lks. 79.86 chs. To section corner

5-1882 Thomas Hunter (P. 377 No. 386), County Surveyor, found remains of old stake but witness trees gone. Set a stone 2" x 10" x 22" in its place.

8-31-1973 County Surveyor dug and easily found 2" x 10" x 22" limestone. Set a CIM over a stone and glass. Corner falls near center of road and 1' east of fence running north.

4-9-2009 County Surveyor found CIM with head broken off down 0.6' in good condition.

4-10-2009 County Surveyor removed CIM w/o head and found 2" x 10" x 22" stone w/iron on north side down 2.3' in good condition. Removed stone and iron and set 5' telspar pipe with Cast Iron Cap down 0.4' at CIM position.