# Certificate of Location of Government Corner

**ID#:** 622006 **Description:** 1/4 SEC COR 19 20 62 **Date Set:** 4/3/2009 **County:** Olmsted

**Section:** 20 **Township:** 106N **Range:** 12W **Monument Description:** 1" square pipe w/cap RLS #15809

**Reference Ties:**

The corner falls in centerline of CSAH 23 and in line with fences east and west
County highway disk in SW side PP #15752 SE 71.70'
Ref pipe W 56.71'
This corner is located by GPS measurement

**Corner History:**

9-1853 Gov't Notes William Jones. 40.00 set post at quarter sec corner. Burr Oak 5 N5E 343. Burr Oak 7 S8E 404. (T.N. = 7.76 S, 8.01 W) (rod over stone = 7.63 S, 6.49 W).

5-1882 T. Hunter P.377 No.368. Corner gone, B tree gone, no visual evidence or knowledge by settlers about corner. Relocated corner M&L on sec line. M&L 39.94-1/2 set boulder stone with small stones around bottom of boulder 2636.37'. 1/16 north set temp stake 19.97-1/4 M&L 1318.18. 1/16 east set marked stake with stone by side on M&L 19.97-1/4 1318.18. 1/16 center NW 1/4 20 set marked stake inters lines.

7-1883 T. Hunter P.384 No.375 found stone P.377.

6-13-1978 County Surveyor dug with backhoe and found a 1/2"x3' rod over a 5"x8"14" boulder with small boulders packed around its base 4' deep. Put pop cans and trash and blacktop around the stone and set the 1/2"x3' rod on the N side of the stone.

6-14-1978 County Surveyor set a 1/2"x2' rod at the road surface over the stone. RP's: Old county highway department disc in SW side PP #15752 SE 71.78. CSD in N side CP W 60.07'. CSD disc in S side telephone pole SW 63.44' (around fe post). Corner in centerline road and in line of fences E and W.

6-20-1995 County Surveyor found 1/2" iron. Set 1" square pipe w/cap 57' west of centerline CR 23 and ± 4' south of fence west. Angle at Ref. pipe, angle RT top center white top on silo NNE to 1/4 corner 19-20 75° 11' 27.5" to 1/4 corner 19-20 (1/2" iron) VA 86° 44' 44" dv 04 slope 56.795 Hor 56.705.

8-23-1995 County Surveyor set PK nail at Ref location from 6-20-95 in new blacktop CR 23.

9-18-1995 county highway department set 1" square pipe w/cap at surface over PK nail.

4-2-2009 County Surveyor found 1" square pipe w/eroded cap at surface in good condition.

4-3-2009 County Surveyor removed 1" square pipe w/eroded cap and set 1" square pipe w/cap down 0.1'.