Certificate of Location of Government Corner

ID#: 622204 **Description:** 1/4 SEC COR 22 27 62 **Date Set:** 9/18/1995 **County:** Olmsted

Section: 22 **Township:** 106N **Range:** 12W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CSAH 23 and 9' west of centerline of field entrance north
State Reference Point in NW side PP #15701 NE 52.33'
Ref pipe SW 109.10'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes West on true line between sections 22 and 27. 40.00 chs. Set quarter section post. Burr Oak 10 in. S 7 1/2ºE 58 lks. Burr Oak 6 in. N 74ºW 91 lks.

4-1890 Thomas Fraser (P. 440 No. 426), County Surveyor, found stake and small stones. Set a stone 6" x 6" x 12" 2' east of railroad line fence.

5-1902 William Fraser (P. 14 Book B), County Surveyor, found stone on line of section corners.

1946 John Kerr (Fieldbook 30 P. 79), County Surveyor, found stone 4' deep.

10-1962 County Highway Department found stone 4' deep.

6-7-1973 County Surveyor found the recorded stone slightly tilted. Reset stone vertical and set a CIM over a 1/2" x 16" iron rod flush with bit. surface.

6-15-1978 County Surveyor dug with the backhoe. Found a spike in old road 3' deep over a 3"x10"x13" shattered limestone 3-1/2' deep. Drove 3/8"x30" rods on the north and south sides of the stone.

6-16-1978 County Surveyor set a 1/2"x13" rod at the road surface over the stone .2 N and 1.25 W of the t.n. The corner is 1/2' S of centerline and 1' west of the fence N. CSD in NW side telephone pole SW 47.10. CSD in W side huge wood fence post N 57.61.

6-19-1995 County Surveyor found CIM. Set 1" square pipe w/cap 45' south of centerline CR 23 and 5-1/2' west of west RR R/W fence. Angle at Ref. pipe, Angle RT light on top white tower to 1/4 cor 22-27 42° 34' 33" to 1/4 corner 22-27 (CIM) VA 89° 14' 51" dv 13. Slope 109.115 Hor 109.10.

9-18-1995 county highway department set 1" square pipe w/cap at surface from 1995 overlay tie out.

4-2-2009 County Surveyor found 1" square pipe w/cap at surface in good condition.