Certificate of Location of Government Corner

ID#: 622306 **Description:** 1/4 SEC COR 22 23 62 **Date Set:** 6/27/2001 **County:** Olmsted

Section: 23 **Township:** 106N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 24 1/2' west of centerline of TH 42 and 58' south of pasture fence west
This corner is located by GPS measurement

Corner History:

9-1853 Gov't Notes: William Jones, 40.00 set post for quarter sec corner. Burr Oak 6 S30E 65. Burr Oak 5 S22W 168.

11-1856 T. Hunter P.18 No.29 used corner, set 1/16 west 19.79-1/2 with 2 B trees on 1/16 corner.

7-1871 T. Hunter P.186 No.197 one B tree standing found stub of old stake by digging. 1/16 east set corner M&L 19.91 (1314l.06) likely for corner 80 rods north S89-3/4°W. 1/16 north set stake M&L 19.94 line east S1/2°E.

8-1887 T. Hunter P.421 No.410 stake set or found P.186 gone reset stone by B tree. meas north 39.92 (2634.72). Meas east 39.82 (2628.12) S89°E. Meas north verified location of corner.

5-2000 County Surveyor determined corner should fall on N-S section line at intersection of 1/4 line from east.

6-27-2001 County Surveyor set telspar pipe w/Cast Iron Cap at computed location.

4-2-2009 County Surveyor found cast iron cap on telspar pipe down 0.2' in good condition.