Certificate of Location of Government Corner

ID#: 622605 **Description:** SEC COR 26 27 34 35 62 **Date Set:** 7/21/2000 **County:** Olmsted

Section: 26 **Township:** 106N **Range:** 12W **Monument Description:** 5/8" copper plug w/punch mark

Reference Ties:

The corner falls 1 1/2' west of centerline of CSAH 7 and 1/2' north of centerline of CR 129
Large hole top S end large CMP ESE 101.04'
Ref pipe W 302.88'
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes William A. Jones, Deputy Surveyor, set post 80.00 chs. North of S Sec. corner 34-35.

5-1902 William Fraser, (P. 14B), County Surveyor, found 3 stones together set for corner and set a 6" x 15" x 34" boulder in their place. Set 1/4 Cor. 27-34 midway and on line. Set 1/16 west of sec. corner M&L. The county highway department had this corner in 1949 and 1967, but it was destroyed when CR 7 was concreted.

6-8-1973 County Surveyor found 1/16 stone west.

8-27-1974 County Surveyor set punch mark in pavement using measurement and line of SW corner Sec. 27 and 1/16 west of SE corner Sec. 27.

11-21-1974 County Surveyor set 1 1/4" iron pipe as corner.

5-16-1997 County Surveyor found 1 1/4" pipe in good condition 1.3' W of centerline CR 7.

5-23-1997 County Surveyor set ref pipe.

6-25-1999 County Surveyor tied out corner.

7-21-2000 County Surveyor set 5/8" copper plug w/punch mark at surface from 1999 tie out.

4-9-2009 County Surveyor found 5/8" copper plug w/punch mark at surface in good condition.