Certificate of Location of Government Corner

ID#: 623404 **Description:** S 1/4 SEC COR 34 62 **Date Set:** 11/30/1994 **County:** Olsmted

Section: 34 **Township:** 106N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is at the surface
The corner falls 33 1/2' south of Schoenfelder's E-W fence and 34' north of south road fence west
60d spike in 5" tree S 17.25'
60d spike in 4" tree ESE 15.00'
Post w/sign 1' north
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes: Ball, Deputy Surveyor. West between 3 and 34. 40.00 set quarter post. Blk. Oak 5 in. N10E 113 lks. Br. Oak 20 in. s58E 410 lks.

4-1863 P.C. Compton P.68 No.96 shows 1/4 post used to set center sec 34 at int lines.

11-30-1994 County Surveyor dug with backhoe in old E-W abandoned road. Much tree grubbing and piling in area. We found 2 stones one 1-1/2"x4"x11" and one 1-1/2"x5"x7" near surface of road 4' east of fence and tree line south and near centerline of old road. The small stone was at clay line. We scraped area and only ran into tree roots. We found nothing further. Set cast iron cap on telspar pipe at smaller stone location. Set post and sign 1' north. RP's: Schoenfelder E-W fence north 33-1/2' S rd fence running west south 34', 60d in 5" tree south 17.25', 60d in 4" tree ESE 15.00'.

10-18-2010 County survey crew found CIC in good condition