Certificate of Location of Government Corner

ID#: 630106 **Description:** 1/4 SEC COR 1 2 63 **Date Set:** 6/12/87 **County:** Olmsted

Section: 01 **Township:** 106N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

Post w/sign 1' north
This corner is located by GPS reference stations "Skins A & B"

Corner History:

10-1853 Gov't notes william A. Jones Deputy Surveyor South on true line between sections 1 and 2 40.20 chs. Set post at quarter section corner 10" Bur Oak North 172 links 7" Bur Oak N 25° E 89 links.

6-1873 Thomas Hunter County Surveyor (Book 3 p. 29030) at 1/4 corner 1-2, found old original 1/4 post standing by side of fence post, tested it by the stump of the North bearing tree and found it correct.

1958 McGhie & Betts at 1/4 corner 1-2 set 1" pipe, packed limestone around it, set 5/8" iron inside. Pipe set by lost methods.

8-1962 John Kerr County Surveyor (Book 85 p. 74) at 1/4 corner 1-2 used corner measured west to center of section 2 2627.5'.

6-3-1982 County Surveyor found pipe with 5/8" re-bar inside at 1/4 corner 1-2. 6-21-1982 dug for old fence post used as reference point by McGhie's in 1958. Found remains of old post, also found remains of another old post 6.0' North.

7-1-1982 County Surveyor dug for more posts to try to prove post found was T. Hunter's fence corner found nothing.

5-18-1987 County Surveyor dug 20' west and 2' south of McGhie iron by using possible bearing tree tie. Found nothing.

6-12-1987 County Surveyor accepted iron set by McGhie & Betts in 1958 as corner. Set telspar pipe and cast iron cap in its place.

10-6-2006 County Surveyor found cast iron cap on telspar pipe up 0.1' in good condition.