Certificate of Location of Government Corner

ID#: 630506 **Description:** 1/4 SEC COR 5 6 63 **Date Set:** 12/11/2003 **County:** Olmsted

Section: 05 **Township:** 106N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 22 1/2' east of centerline of NBL of CSAH 22 and 88' south of centerline of RCC entrance west
County highway disk in PP #23138 SE 63.66'
Ref pipe (RCC) NW 271.85'
Post w/sign 2' east
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes: William Jones; 38.78 set post at quarter section corner and made trench.

6-1896 Hunter, Deputy Surveyor (Pg603 No 548) S6 Halburt, Coe; Corner gone, found remains of old corner fence post which Mr Geo Cook avers was where old stake stood. 16 West set stake M&L 19.85'

9-13-1965 J. Kerr found stone 5x13x16 with cross beside post remains and set C.I.M. over 1/2"x2' rod at this location.

1966 J. Kerr replaced C.I.M. after grading. Found rod (likely rod placed below C.I.M..

11-10-1972 County Surveyor found C.I.M..

7-1979 County Surveyor shot corner in control survey.

3-11-1989 County Surveyor found CIM in good condition. Used in city of Rochester mapping project survey.

6-19-1989 County Surveyor found CIM in good condition.

1-4-1990 County Surveyor used CIM in photo control survey.

5-15-1995 county highway department referenced monument before grading of CSAH 22

10-10-1995 county highway department set 1" square pipe with cap #15809

3-2-1999 County Surveyor found 1" square pipe w/cap in good condition down 0.5'.

12-1-2003 County Surveyor found 1" square pipe w/broken cap down 0.5' in good condition.

12-11-2003 County Surveyor removed 1" square pipe w/broken cap and set 6' telspar pipe w/cast iron cap down 0.4'. Set post w/sign 2' East.