# Certificate of Location of Government Corner

**ID#:** 630604 **Description:** 1/4 SEC COR 6 7 63 **Date Set:** 3/28/1988 **County:** Olmsted

**Section:** 06 **Township:** 106N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #15809

**Reference Ties:**

The corner falls in centerline of CR 144
County Survey Disk in PP NE 54.43'
This corner is located by GPS measurement

**Corner History:**

1853 Gov't Notes, William Jones; 38.80 set post at 1/4 section post. RPs- 12" burr oak S27W 129, 8" burr oak N38 E 134.

6-1856 T. Hunter Pg.10 No.16 shows 1/4 post

6-1896 W.Fraser by Hunter, Pg.603 No.548; found stone.

? Corner found and referenced, road cut repeatedly. Iron pipe retained as corner in road near bed rock. RPs- spud in hub 24" burr oak ENE 83.62, spud in hub in 12" burr oak NNW 80.53.

1940 J.Kerr Bk.17 No.44-45; Shows stone on dwg. Took new bearing trees; AZ 130°50' 59.0' 18" burr oak, 61°25' 49.5' 6" burr oak, 347°35' 25.0' 14" burr oak.

5-1963 J. Kerr 1/2" pipe near bedrock. RPs- spike in hub in 24" oak tree ENE 83.62, spike in hub in 12" oak tree NNW 80.53.

1969 county highway department align notes call for CIM at this corner. I couldn't find out when the CIM was set and by whom.+

3-28-1988 County Surveyor set 1" square pipe/cap over 1/2" pipe used as corner. Corner falls in a 8' to 10' cut on south side of road. RP-CSD in pp NE 54.43.

3-10-1989 County Surveryor found 1" square pipe w/cap. Used in City of Rochester mapping project survey.

12-4-2003 County Surveyor found 1" square pipe w/cap at surface in good condition.

9-17-2007 County Surveyor found 1" square pipe w/busted cap down 0.2' in good condition. Replaced cap.