Certificate of Location of Government Corner

ID#: 631505 **Description:** SEC COR 15 16 21 22 63 **Date Set:** 11/16/1994 **County:** Olmsted

Section: 15 **Township:** 106N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The monument is down 0.7'
The corner falls in centerline of CSAH 11
County highway disk in PP SE 61.57'
Ref pipe W 65.88'
This corner is located by GPS measurement

Corner History:

NO RECORDS

10-16-1962 J. Kerr found 1" pipe riser set in stoney grade of road. RPs- spike 16" oak stump E 36.55, spike pp SE 34.33, spike pp NW 49.70, 1/2" rod on transit line to knot in top light pole in yard slightly east of due NE 150'.

10-1962 County Highway Department, Bk.281, RPs- spike & disc in top of corner post E 61.54', spike & disc in pp ESE 61.55', spike & disc in 30" oak ENE 75.57'

9-1963 J. Kerr, run line east to 1/4 15-22, set stake M & L.

5-8-1989 County Surveyor found brass washer with nail in centerline CR 11. Found 1/2" pipe down .3'. Removed 1/2" pipe and found CIM. Checked old county highway department disc in pp SE 61.57', other old pp ties gone.

6-22-1994 County Highway crew found CIM 6" deep. Set 1" square pipe w/cap W of corner near top of hill. For reference before cold recycling bituminous surface of CR 11

11-16-1994 County Highway Department set 1" square pipe w/cap at surface from 1994 overlay tie out.

2-13-2004 County survey crew found 1" square pipe w/cap at surface in good condition.

7-12-2005 County survey crew found 1" square pipe w/cap at surface in good condition.

3-7-2012 County survey crew found 1" square pipe with cap at surface in good condition. Lowered pipe and cap in preparation for bituminous road overlay.