# Certificate of Location of Government Corner

**ID#:** 631704 **Description:** 1/4 SEC COR 17 20 63 **Date Set:** 10/20/2000 **County:** Olmsted

**Section:** 17 **Township:** 106N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #15809

**Reference Ties:**

The corner falls in centerline of twp road east and 1' east of centerline of N-S twp road
County Survey Disk in TP SE 59.56'
Punch hole in W end 15" CMP SSW 84.90'
County Survey Disk in PP #18306 W 30.33'
This corner is located by GPS measurement

**Corner History:**

10-1853 Gov't Notes: William A. Jones, Deputy Surveyor West on true line between sections 17 and 20. 39.90 chs. Set post at quarter section corner. Burr Oak 9 in. N14°E 25 lks. Burr Oak 11 in. S17°W 40 lks. 79.80 chs. To section corner.

1856 Thomas Hunter (Book A P. 7 No. 11), County Surveyor, used the corner to set the 1/16th North, the center 17, and the 1/16th North of the center 17.

4-1882 T. Hunter (Book A P. 376) dug in the center of the roads N-S-E. He found the remains of the old stake. Set a new Burr Oak stake, marked.

5-1953 John Kerr (card), County Surveyor, found the remains of the stake P. 376 with the point in clay soil. Set a 1 1/4" pipe driven through the old stake.

8-26-1963 J. Kerr set a C.I.M. over the pipe set in the stake remains in 1953.

9-10-1967 J. Kerr (certificate filed) reset a C.I.M. over the pipe in the old stake remains.

4-12-1978 The County Surveyor dug down to Kerr's C.I.M. and found it broken. Replaced it with a new C.I.M.

6-5-1989 County Surveyor found CIM in good condition. Used in City of Rochester mapping project survey.

10-20-2000 County Surveyor found broken CIM down 0.6'. Removed CIM and set 1" square pipe w/cap at surface.

9-16-2003 GGG, Inc. found and used monument.