Certificate of Location of Government Corner

ID#: 631805 **Description:** W SEC COR 18 19 63 **Date Set:** 3/29/1989 **County:** Olmsted

Section: 18 **Township:** 106N **Range:** 13W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls on top of slope of ditches north and west
County Survey Disk in PP #17962 N 27.01'
Post w/sign 2' north
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, William Jones; 80.0 set post corner to section 13-18-19-24. RPs- 5" black oak S°W52 links, 6" black oak N2°W262 links, 14" burr oak S47°E97 links, 12" black oak N1°E244 links.

4-1898 W.Fraser Pg.622 No.565; Set stone 5x6x40 in place of remains of fence post.

5-12-1961 J. Kerr found a limestone monument and Iron pipe. Set CIM over limestone. Corner lies on south side large red cedar corner post.

3-1988 County Surveyor found bottom plate of CIM in frozen ground. Will reset over stone. It falls on north side of newer fence post.

3-1989 County Surveyor dug out CIM & found stone beneath. Set 16" CIM over stone. Monument is 0.5' north of face of wood junction post in line of fence N-S. The corner lines with south edge of ditch running west. RP- CSD in pp# 17962 N 27.01'.

11-28-2001 County Surveyor found CIM at surface in good condition.

10-7-2002 County Surveyor found CIM at surface in good condition.

7-28-2003 County Surveyor found CIM at surface in good condition. Set post w/sign 2' north.