Certificate of Location of Government Corner

ID#: 631809 **Description:** SEC CEN 18 63 **Date Set:** **County:** Olmsted

Section: 18 **Township:** 106N **Range:** 13W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.
1/2" rod inside 3/4" pipe

Reference Ties:

The corner falls 6' east of line of large oaks south and 11' west of centerline of N-S ditch
County Survey Disk in E side 18" Burr Oak N 9.43'
County Survey Disk in NE side 16" Burr Oak NW 6.31'
Post w/sign 2' east
This corner is located by GPS reference stations "Leaning A & B"

Corner History:

4-4-1898 W.Fraser Pg.622 No.565; Set stone 2x8x24 at intersecting quarter lines.

11-1-1950 J. Kerr ran quarter lines and placed an iron rod driven into the rock with limestone on top of it marked X.

12-13-1957 J. Kerr found and used limestone.

5-3-1989 County Surveyor found 1/2" rod inside 3/4" pipe packed in limestone pieces. RPs-iron is approx. 6' east of line of large oaks running S & 11' west of center of ditch running N-S, spike & CSD in east side 18" burr oak N9.43, spike & CSD in NE side 16" burr oak NW 6.31.

4-8-1999 V. Fangman found and used 1/2" rod inside 3/4" pipe.

7-18-1999 GGG used computed center.

8-29-2000 GGG found and used 1/2" rod inside 3/4" pipe.

12-28-2001 Brand & Massey Surveying Inc. found and used 3/4" pipe at center of section 18.

1-14-2005 Massey Land Surveying found and used 1/2" rod inside 3/4" pipe.

7-14-2005 County Surveyor found 1/2" rod inside 3/4" pipe in good condition up 0.2'. Set sign & post 2' east. Did not check ties.