Certificate of Location of Government Corner

ID#: 631909 **Description:** SEC CEN 19 63 **Date Set:** 9/15/1978 **County:** Olmsted

Section: 19 **Township:** 106N **Range:** 13W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.
5/8" pipe w/cap RLS #11622

Reference Ties:

The monument is up 0.1'
The corner falls 13 1/2' south of E-W fence and 1/2' west of N-S fence
Sign on fence post 1/2' east
This corner is located by GPS reference stations "Round Trip A & B"

Corner History:

No records. Should be corner of four land properties. State may have accepted corner there. Likely corner post of 4-way fences.

9-15-1978 McGhie & Betts set 5/8" w/cap pipe #11622 at intersecting quarter lines.

8-4-2005 County Surveyor did not find 5/8" pipe but did find 60d spike w/ribbon leaning on NW side of corner post for fences N-S-E-W.

11-15-2007 County Surveyor found 5/8" pipe (no cap) at surface in good condition. Set sign on W side of post.

8-31-2011 County survey crew found 5/8" pipe in good condition