Certificate of Location of Government Corner

ID#: 632005 **Description:** SEC COR 19 20 29 30 63 **Date Set:** 8/13/2007 **County:** Olmsted

Section: 20 **Township:** 106N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in centerline of CR 101 and in line with fence west
1/2" rod under the fence W 99.83'
County Survey Disk in PP #46353 E 34.73'
This corner is located by GPS measurement

Corner History:

No records at courthouse record books.

1853 Gov't Notes, William Jones; 80.0 set section post at corner to section 19,20,29,30. Deposited charcoal, made mound, trench, pits, and planted cherry seeds NE,SW,SE, & NW.

1957 McGhie & Co set a 1 1/4" pipe by measurements. RPs- 100' west under fence.

9-7-1971 County Surveyor found 1/2" RP rod and pipe. Set CIM over pipe & glass. RPs- 100' rod now west 99.83, 32.5' west to center 6" cedar corner post, 149.2' SSE to center smashed in 18" galv. Culvert east end, no mark.

6-21-1989 County Surveyor found CIM in good condition. Used in City of Rochester mapping project survey.

5-19-2004 County Surveyor found CIM down 1.5' in good condition.

8-13-2007 County Surveyor found CIM w/head broken off down 1.5' in good condition. Removed CIM and found 1 1/2" pipe down 3.3' in good condition. Removed pipe and set 6' telspar pipe w/cast iron cap down 0.4'.