Certificate of Location of Government Corner

ID#: 632206 **Description:** 1/4 SEC COR 21 22 63 **Date Set:** 11/16/1994 **County:** Olmsted

Section: 22 **Township:** 106N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The monument is down 0.7'
The corner falls in centerline of CSAH 11 and in line with fences east and west
County Survey Disk in PP #38218 NE 87.50'
County Survey Disk in CP E 60.37'
Ref pipe W 43.43'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, William Jones; 40.0 set 1/4 section post to 1/4 section corner and made trench. RP- 14" burr oak N70 1/2 W220.

10-1941 A. Armstrong; Used E-W fence line as section line.

9-19-46 John Kerr set 1 1/2" pipe M & L.

10-30-1947 J. Kerr found 1 1/2" iron pipe 0.6 ft. down.

1963 County Highway Department found 1 1/4" pipe. Set 3/4" riser.

? County Highway Department spike & disc in pp NE 88.12' (3/4" rod) ?

1969 County Surveyor found C.I.M. set by County Highway Department. All RPs before and after grading are gone.(5-1989)

5-4-1989 County Surveyor found C.I.M. in centerline CR 11 RP's CSD in PP #38218 NE 87.50'. CSD in C.P. E 60.37'.

6-22-1994 County Highway crew reference corner before cold recycling bituminous surface of CR 11.

11-16-1994 County Highway Department set 1" square pipe w/cap at surface from 1994 overlay tie out.

8-3-2005 County survey crew found 1" square pipe w/cap at surface in good condition.

3-7-2012 County survey crew found 1" square pipe with cap at the surface in good condition. Lowered pipe and cap in preparation for bituminous road overlay.