Certificate of Location of Government Corner

ID#: 632406 **Description:** 1/4 SEC COR 23 24 63 **Date Set:** 11/9/2006 **County:** Olmsted

Section: 24 **Township:** 106N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in cenerline of N-S twp road and 7' south of centerline of farm driveway east
County Survey Disk in PP NNW 111.26'
Hard nail in knot in 12" Pine NW 78.7'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, William Jones; 40.0 set section post of 1/4 section corner. RPs- 6" red oak S86 W203, 8" burr oak S50 E250.

4-1884 T. Hunter Pg.387 No 378; corner gone, bearing trees gone and no evidence. Set stake M & L between stones on west side S24.

5-1884 T. Hunter Pg.389 No.380; found stake.

6-1901 R.Fraser Pg.706 No.620; found stake and stones on direct section line.

1935 county highway department book 87 page 71 found rotted wood stake. Drove drill steel 1" beside stake as marker. Stake found 2' deep in stones. Set 1" drill steel beside marker. RPs- corner fence post NW 48.8', tele pole E 25.6', fence post SW 49.7'.

8-13-1969 J.Kerr; set CIM on same northing and southing as drill steel, but .2' east of drill steel to make CIM on direct line. RPs- coke cap in tele pole SE 76.9', hard nail in knot on south side pine, most Sely NW 78.7', MHD in pp# 16145 east side NNW 111.0'.

9-26-2006 County Surveyor found PK nail at surface, removed PK nail and found CIM down 0.7' in good condition.

11-6-2006 County Surveyor removed CIM and probed stones down 2.6'.

11-9-2006 County Surveyor set 1" square pipe w/cap at surface at CIM location.