Certificate of Location of Government Corner

ID#: 632804 **Description:** 1/4 SEC COR 28 33 63 **Date Set:** 8/28/1980 **County:** Olmsted

Section: 28 **Township:** 106N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in line with fence south and 1' west of old CP
County Survey Disk in W side brace post S 30.13'
Post w/sign 1' west
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes; William A. Jones, Deputy Surveyor. West on true line between sections 28 and 33. 40.04 chs. Set post at quarter section corner, deposited charcoal and made mound, & trench with pits and planted cherry seeds NE and SW. 80.08 chs to section corner.

5 thru 11-1872 Thomas Hunter, County Surveyor, (Bk A, Pg 198, No. 208, Old Fieldbook 2, Pg 10, and old Fieldbook 1, Pg 15) "found fence post set near another fence post near the intersection of two fences, said post being set in the center of the original mound according to the testimony of Cavanaugh who says he set the post." He used this corner to set the 1/16 South, a stake midway (20.03 chs.) and on line to the Center 33, a temporary stake, set at intersecting 1/4 lines. He also set the 1/16 north, a stake midway (19.70 chs) and on line to the Center 28, a temporary stake, set at intersecting 1/4 lines.

6-1877 T. Hunter (Bk A, Pg 316, No. 310, Old Fieldbook 5, Pg 14, and Old Fieldbook 4, Pg 174-175) "found fence post, corner of fence. Set where 1/4 post stood by Cavanaugh as described in Survey No. 208." He used this corner to set the Center 33, a stake, set midway (20.03 1/4 chs.) and on line to Section Corner 28-29-32-33.

1947 John Kerr (Kerr Bk 34, Pg. 39) shows "stone on top of remains of fence post near intersection of fences."

8-28-1980 County Surveyor dug for this corner. Found a 7"x8"x12" boulder with remains of stake on the south side. Removed boulder and stake and found them over a dark spot (possible post mark). Set a telspar pipe with a cast iron cap over a 1" sq by 35" pipe friven where the stake stood. Set the boulder back on the north side of the pipe. We also dug midway and on line to the computed location of the Center 28 and found a 12" square mark extending 1' down into clay at this location.

6-29-1989 County Surveyor found cast iron cap on telspar pipe in good condition.

8-17-2005 County Surveyor found cast iron cap on telspar pipe down 0.2' in good condition.