Certificate of Location of Government Corner

ID#: 633306 **Description:** 1/4 SEC COR 32 33 63 **Date Set:** 10/16/2000 **County:** Olmsted

Section: 33 **Township:** 106N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 1/2' north of centerline of CR 111 and in line with fences north and south
County highway disk in SE side PP #17617 NE 66.47'
County Survey Disk in Box Elder NNW 99.51'
Ref pipe S 55.47'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, William Jones; 40.0 set quarter section post and deposited charcoal, made mound, trench, pits, and planted cherry seeds NE & SW.

5-1872 T.Hunter Pg.198 No.208; Found short stake in mound in center road.

6-1877 T.Hunter Pg.316 No.310; Found remains of old stake. Set stone in its place.

5-1952 J.Kerr Bk. 55 Pg. 16 meas. mile from SE 32 north 5283.75, found stake at SE 32 dug 7'x14' and found 1/4 32-33. Found recorded stone broken in half and leaning. Found marks in soil where excavation had been made to set corner. It came midway 2641.87. Set rod 50' south under fence. Corner 1' W line fence couth. Fence corner shown as NE cor.32. Set rod & referenced.

7-6-1965 J.Kerr set CIM over 1/2"x18" rod. RPs- spud in pp NE 53.6, spud in corner fence post N 29.5, corner lies 2' north of center of traveled road, & 1' west of fence south.

4-1976 County Surveyor found corner ok. Left rod inplace and removed CIM. L.R.P.-nail E 16.36 S 13.93.

7-1977 County Surveyor set CIM at E-W nail and at 99.51 from spike & CSD in box elder NNW taken in 1976. Corner in centerline E-W road and in line with fence N & S. RP- Old disc in SE side PP #17617 NE 66.51.

5-23-2000 County Surveyor found CIM down 1.4' in good condition. Set ref pipe and tied out corner.

10-16-2000 County Surveyor set 1" square pipe w/cap at surface from 2000 tie out.

8-22-2005 County Surveyor found 1" square pipe w/eroded cap at surface in good condition. Replaced cap at surface.