Certificate of Location of Government Corner

ID#: 640605 **Description:** W SEC COR 6 7 64 **Date Set:** 8/6/2007 **County:** Olmsted

Section: 06 **Township:** 106N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 10' west of centerline of CR 104 and 9 1/2' north of centerline of twp road west
County Survey Disk in NW side PP #52430 SW 50.28'
County Survey Disk in SW side PP #52431 SE 67.13'
This corner is located by GPS measurement

Corner History:

Gov't. Notes Section post for corner. Built mound, trench, drove cherry stake in center. Planted S.E. osage orange & N.E. apple seeds.

4-1856 Thomas Hunter shows section corner, 1/16 east 17.50 chains then 20 chains to 1/4 post, bearing trees to 1/16 corner (N 143/4°E 37 lks.) & (S 55° E 36 lks.)

12-1857 Thomas Hunter Pg. 40 No. 62 Shows section corner, 1/16 north 19.81 chs. M&L to 1/4 post, 1/16 west 19.97 chs. M&L to 1/4 post, 1/16 south 19.82 chs. M&L to 1/4 post, (Bts. To 1/16 corner, N 62° E 71 lks. S 57° E 10 lks.), 1/16 east 17.20 chains then 20 chains to 1/4 post.

2-1882 T. Hunter, P. 375 No. 366 found stone, avered by Mr. Brooks & others as set from original corner. Bearing tree gone. Likely found stake used by Hunter P. 40 which placed 1/16 cor. 19.97 west and 19.81 north.

4-1902 C. Armstrong P. 34 B found limestone 11/2 x 18 x 18 in line fence east. Measure west 40.15 to stone set from stake 1/16 north set oak stake 19.91 or 19.81.

5-1961 J. Kerr B.84 P.21 found stone. Set CIM over limestone, 1/2" rod 2.5' south of fence corner E 40.0, 1/2" rod 3.0' south of fence corner SW 50.0, corner lies 4' west & 4' north crossroads., 16 north set rod M&L comes in west ditch, POT set on line 1516.75 or 204.95 N. of 1/16.

8-26-1970 County Surveyor found 1/16 iron & POT pipe, 1/16 came 3' south of fence west - set hard nail in corner post top E 59.0. Came 12' west of West edge road as in place.

5-4-1989 County Surveyor set Ref. Pipe 182.46' W. of section corner before road grading C.R. #104.

7-1-1993 County Surveyor set P.K. nail @ corner location. Corner is 7' north of centerline twp. Road west & 10' west of centerline CR #104.

7-2-1993 County Surveyor set 1" square pipe w/cap as corner in blacktop CR #104.

2-11-2002 County Surveyor found 1" square pipe w/cap at surface in good condition.

4-3-2006 County Surveyor found 1" square pipe w/cap at surface in good condition.

5-18-2007 County Surveyor found 1" square pipe w/cap at surface in good condition.

8-6-2007 County Surveyor set 1" square pipe w/cap at surface from 2007 overlay tie out.