Certificate of Location of Government Corner

ID#: 641206 **Description:** 1/4 SEC COR 11 12 64 **Date Set:** 5/16/1997 **County:** Olmsted

Section: 12 **Township:** 106N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 1' east of centerline of 3rd Ave SE, 15' south of centerline of 16th St SE and 16 1/2' south of center of manhole
County Survey Disk in PP #03903 SW 41.20'
County Survey Disk in PP #04092 SE 36.15'
This corner is located by GPS measurement

Corner History:

Gov't Notes 40.00 set section post with trench. RP-Burr Oak 8N 10E 175 lks.

5-1859 T. Hunter Pg. 59 No. 85 - measure east 39.97 chains to center section.

1960's ? - 5/8" x 42" rod in place in black top. No sign of stone. Set 1/2"x2' rod below long CIM. RPs- NE corner brick garage add. SW 63.75, Block corner 5/8" rod SE 46.72 Center top of hydrant screw NE 63.43, Approx. center manhole N 16.6

4-7-1970 County Surveyor set CIM over 1/2"x2' rod.

6-18-1973 County Surveyor reset CIM over 3/4"x11" rod flush with bituminous.

5-16-1997 County Surveyor set 1" square pipe w/cap in intersection of 3rd Ave. SE & 16th St. SE.

10-3-2002 County Surveyor found 1" square pipe w/cap at surface in good condition.

4-8-2004 County Surveyor found 1" square pipe w/cap. Cap was worn smooth with no center divot evident at surface.

4-3-2006 County Surveyor found 1" square pipe w/smooth cap at surface in good condition.

3-26-2007 County Surveyor found 1" square pipe with smooth broken cap. Removed cap, lowered pipe and reset cap.

2-26-2010 Ken Manahan, Mn/DOT Crew Chief, found 1" square pipe w/cap in good condition.