Certificate of Location of Government Corner

ID#: 641305 **Description:** SEC COR 13 14 23 24 64 **Date Set:** 8/29/2007 **County:** Olmsted

Section: 13 **Township:** 106N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in Menards yard, 19' south of south face of building wall, 35' east of east face of building and 9 1/2' east of centerline of door #10
This corner is located by GPS reference stations "Menards A & B"

Corner History:

7-1854 Gov't Notes, W.B. Yerby Deputy Surveyor 80.00 chs s et a post in mound of earth and sod, made trench and pits. Deposited charcoal, planted osage orange seeds NE and SW.

12-1875 Thomas Hunter, County Surveyor (Pg 289, No. 285) Found cedar stake driven by Holden Smith at remains of corner post found in 1874. Chained West 39.68, chained North 19.93 chs. set stake then 19.93 chs. to board fence running east and west avered by S. Olin that quarter post stood in its mound in said fence.

6-1857 Thomas Hunter (Pg 31, No. 48) Chained North 19.93 then 19.93 to quarter post.

5-1874 Thomas Hunter, County Surveyor (Pg 250, No. 251) Section corner missing or lying on the ground beside what had the appearance of being a mound, found the remains of old corner post to fences north and west, used corner post chained 19.97 1/2 south set staken then 19.97 1/2. Chained east 19.88 set stake then 19.88 chs. Chained west 39.68 to stake set midway and on line.

5-1895 William Fraser, County Surveyor (Pg 566, No. 519) Found cedar stake set by Holden Smith. Set stone 18" x 6" x 3" on west side of stake. Chained west 19.82 set stone and stake midway and on line to quarter corner. Chained east 19.87. Could not find stake set in 1874, set stone midway and on line to quarter corner. Chained south 19.97 1/2 set stone next to stake set by Hunter in 1874.

11-1963 John Kerr, County Surveyor (Cert. filed) Found limestone and cedar stake. Set C.I.M. over 1" x 30" pipe and cedar stake. Measured north set sixteenth pipe midway and on line 1315.85'.

9-18-1980 County Surveyor took ties to C.I.M. before water main construction. RPs-C.S.D. in P.P. NW 152.03'. C.S.D. in P.P. NE 134.05'.

3-28-89 County Surveyor set a 5' telspar pipe with cast iron cap from ties taken 9-18-1980. RPs- CSD in pp 152.03, CSD in pp NE 134.05, "V" in manhole ring 15.25, CSD in west side pp north 34.18, face of C.P. SW 0.5'.

7-16-1996 County Surveyor found C.I.C./p2 in good condition. Set 1" sq. pipe w/cap as reference on north side off ramp to Hwy. 52 in NE1/4 Sec. 23 106-14 North edge conc. ramp SW 15.5', broadway owe sign NW 16.7'. NE ref. pipe.

Summer-1997 Note by County Surveyor, corner may fall under new Menards Building.

8-15-2001 Mn/DOT survey crew found 1" square pipe w/cap reference to section corner in good condition.

8-29-2007 County Surveyor set 1" square pipe w/cap at surface from GPS and traverse data.