Certificate of Location of Government Corner

ID#: 641309 **Description:** SEC CEN 13 64 **Date Set:** **County:** Olmsted

Section: 13 **Township:** 106N **Range:** 14W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.
2" pipe

Reference Ties:

The corner falls in line with old fence posts south and 2 1/2' north of old fence posts E-W
County Survey Disk in W side 14" Poplar N 30.21'
County Survey Disk in S side 14" Poplar WNW 29.72'
Post w/sign 2' South
This corner is located by GPS measurement

Corner History:

6-4-1857 Thomas Hunter, Pg. 31, No. 48 Shows center section 1/16 corner south 19.88 M&L.

10-18-1895 William Fraser, P. 583 No. 532 S13 Took avered corner post as corner. West set stone at 13.76 (908.16 then 1712.04) or 25.94 west to W1/4 13 total 2620.20.

10-10-1948 J. Kerr found and used 2" pipe.

1950's J. Kerr run inters lines. Set 3" or 4" pipe up above ground for Libby lands survey. Came near fence corner.

5-12-1961 J. Kerr found and used 2" pipe.

12-30-1977 McGhie & Betts found and used 2" pipe.

10-6-1982 Yaggy Associates found and used 2" pipe.

12-15-1983 Land Consultants found and used pipe for Willow Creek First Subdivision plat

3-29-1989 County Surveyor found 2" I.D. pipe with mashed top up 4" above ground N.E. of Libby's dike in line of old fence posts south and 2.5' north of old fence post.

10-30-2002 County Surveyor found 2" pipe with mashed top up 0.3' in good condition.

10-30-2002 Mn/DOT Survey Crew found monument in good condition.

3-7-2003 County Surveyor set post w/sign 2' South.