Certificate of Location of Government Corner

ID#: 641905 **Description:** W SEC COR 19 30 64 **Date Set:** 4/19/2001 **County:** Olmsted

Section: 19 **Township:** 106N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CR 104 and 1' south of centerline of CR 117 east
Ref. iron ENE 192.22'
County Survey Disk in PP NE 67.73'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes - Yerby, 80.00 set section post, built mound, trench & charred stake.

5-1872 T. Hunter; P. 200 No. 204, found stone in center road as section corner.

6-1889 T. Fraser, P. 433 No. 420, found stone and stake set by Hunter. Set boulder 10"x16"x22" in place of Hunter's stone.

10-17&21-1968 John Kerr, Found triangular boulder & hub. Set CIM at inter true line and line from east 1"x30" conduit below. Fraser record east 2545.45, actual 2552.55 (See S1/4 19).

11-22-1988 County Surveyor set 16" CIM over monument deep in CR #104 6' east of 8 N-S road and 1' South of centerline CR#117 east.

7-23-1996 County Highway Department Tied out corner for CR 104 grading. Set 5/8" re-rod in s. , Left CIM in place.

12-1-1998 County Surveyor set 120d spike in crushed rock C.R. #104 as corner from 1996 reference tie.

4-19-2001 County Surveyor set 1" square pipe with cap at surface from 1996 tie out.

2-7-2005 County Surveyor found 1" square pipe w/cap at surface in good condition.

4-3-2006 County Surveyor found 1" square pipe w/cap at surface in good condition.