Certificate of Location of Government Corner

ID#: 641906 **Description:** W 1/4 SEC COR 19 64 **Date Set:** 4/19/2001 **County:** Olmsted

Section: 19 **Township:** 106N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CR 104, 10' south of fence west and in line with fence east
Ref. pipe WNW 74.33'
County Survey Disk in PP SW 76.13'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes - Yerby, 40.00 set section post, charred stake, mound, trench, and Osage Orange seed planted SE and apple seeds NE.

11-1857 T. Hunter Pg. No. 61, measure East 38.92 to center section 19.

5-1872 T. Hunter P. 200 No. 209 found stake center road.

6-1874 T. Hunter P. 255 No. 255, found stake center road P. 200.

4-1898 W. Fraser P. 624, No. 566, found stone in center road set in 1894 in survey replacing stake P. 255 (no measure). Stone lies in line fence East and West.

4-1923 J. Kerr, P. 390B, found stone, drove iron rod through old stake between stones. Measure East 2566' to center 19 set as corner. Measure North 2540.85 to NW 19, 1/16 center NW 1/4 19 set stone 1326.4 E to 1/16, 1320.27 N to 1/16.

10-1968 J. Kerr found stone. Set CIM over rod. Corner lies 2.0' W center traveled road (1968).

7-17-1989 County Surveyor found CIM in good condition.

7-19-1996 County Highway Department tied out corner for C.R. #104 grading. Set 1" square pipe w/cap and sign 74' West of corner. NE corner edge grey shed (not overhang) SE to W 1/4 corner 314.01' 28" Hor. 74.325. Removed CIM.

12-1-1998 County Surveyor set 120d spike as corner in crushed rock C.R. #104 from 1996 corner reference tie.

4-19-2001 County Surveyor set 1" square pipe with cap at surface from 1996 tie out.

2-7-2005 County Surveyor found 1" square pipe w/cap at surface in good condition.

10-4-2006 County Surveyor found 1" square pipe w/cap at surface in good condition.