Certificate of Location of Government Corner

ID#: 642204 **Description:** 1/4 SEC COR 22 27 64 **Date Set:** 10/5/2007 **County:** Olmsted

Section: 22 **Township:** 106N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CR 147 north and 2' south of centerline of CR 147 east
County Survey Disk in W side PP #35889 NE 76.75'
County Survey Disk in NE side PP #35882 SE 42.77'
This corner is located by GPS reference stations "Starburst A & B"

Corner History:

1854 Gov't Notes - W.B Yerby, East random 22&27, 40.00 set temp section post west between section 22 & 27.
40.00 set section post course 9° 08' E with trench. RPs-Burr Oak 7 S 78 W lks.

12-1874 T. Hunter P. 266 No. 264, found original stake, measure north 40.03.

5-1875 T. Hunter P. 274 No. 272 found original stake, measure west 39.70, Burr Oak S 271/2 W 83L (54.78').

6-1903 C. Armstrong P. 64 B used corner to set stone at center 27, Marked stake on plat - No measure.

4-1905 C. Armstrong P.98 B found stake, set stone 11/2"x16"x18", measure east 39.64, north 39.94. Corner found from scribed bearing tree set 2" pipe, beg old nails, glass, etc.

8-22-1963 J. Kerr set CIM over pipe, old nails, glass, etc. Corner lies center road north, some south center E-W road, original corner very deep.

7-12-1974 County Surveyor reset "Shorty" CIM flush with bituminous surface.

7-1989 County Surveyor found CIM in good condition.

8-15-2001 Mn/DOT survey crew found CIM in good condition.

10-1-2002 County Surveyor found CIM down 0.5' in good condition.

10-5-2007 County Surveyor did not find CIM, destroyed by road regrade. Set 1" square pipe w/cap at surface from computed coordinates. CSD in W side of PP #35889 NE 76.75' & CSD in NE side of PP #35882 SE 42.77'.