Certificate of Location of Government Corner

ID#: 650304 **Description:** 1/4 SEC COR 3 10 65 **Date Set:** 8/4/2000 **County:** Olmsted

Section: 03 **Township:** 106N **Range:** 15W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 7 1/2' north of centerline twp road east and 4 1/2' west of centerline of CSAH 3
County Survey Disk in SE side PP #40144 NE 56.02'
County Survey Disk in NW side PP SW 50.00'
County Survey Disk in SW side PP NW 55.04'
Ref pipe NE 63.12'
This corner is located by GPS measurement

Corner History:

6-1854 Gov't Notes Michael G. Karrick Deputy Surveyor West on true line between sections 3 and 10. 40.00 chs set quarter section post in mound with trench and pits and charred stake. Planted osage orange seeds N.E. and S.W.

5-1867 H.E. Horton County Surveyor (P.83 No.126) used 1/4 corner measured North 19.98 1/2 chains to 1/16 corner then 19.98 1/2 chains to center of section 3.

6-19-1930 County Highway Department (BK 56 P.54) found stone 8" x 15" x 15" pointed 2.2' West of center line of road.

1962 John Kerr County Surveyor (Bk.86 P.29) set harrow tooth in centerline of blacktop road and on line from centerline of road at NE corner of section 10 and a fence corner at NW corner of section 10.

6-14-1984 County Surveyor dug North of Kerr's C.I.M. found Easterly end of County Highway Department's 1930 dig, so dug West found stone 5" x 10" x 12" standing on edge, found pieces of metal around and beneath stone, also found 6" long square nail. Set 120d spike and re-rod by stone which is 7.72' North and 4.46' West of Kerr's C.I.M.

6-20-1984 County Surveyor set C.I.M. over 1/2" re-rod over stone found. Removed Kerr's C.I.M. and 1/2" rod below.

6-3-1999 County Surveyor found CIM in good condition. Set ref pipe and tied out corner.

8-4-2000 County Surveyor set 1" square pipe w/cap at surface from 1999 tie out.

2-2-2005 County Surveyor found 1" square pipe w/cap at surface in good condition. New pp's SW and NW.

7-14-2006 County Surveyor found 1" square pipe at surface in good condition.