Certificate of Location of Government Corner

ID#: 651004 **Description:** 1/4 SEC COR 10 15 65 **Date Set:** 8/4/2000 **County:** Olmsted

Section: 10 **Township:** 106N **Range:** 15W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 1/2' west of centerline of CSAH 3, 2' south of centerline of township road east (20th St SW) and in line with fence and pole line west
The monument is at the surface
County Survey Disc in NW side PP #40161 NE 55.98'
County Survey Disc in NE side PP SE 54.73'
County Survey Disc in S side PP #40162 SSW 55.35'
Ref pipe SE 59.66'
This corner is located by GPS measurement

Corner History:

6-6-1854 Michael G. Karrick, Deputy Surveyor, measured west 40.00 chains on true line between Sections 10 and 15. Set quarter section post in mound with trench, pits and charred stake. Planted Osage Orange seeds NE and SW.

8-10-1857 E.P. Bircher, by John B. Fellows, Deputy, (Old Road Book, Page 72, Road No. 76 and New Road Book, Page 178, Road No. 76), used quarter post for road survey.

4-17-1911 Charles Larson, County Surveyor, (Book B, Pages 154-155), found limestone.

7-8-1930 County Highway Department, (CHD Book No. 56, Page 53), dug and found nothing. Set hub at assumed corner. P.I. Sta. 27+35.00. RPs - Spike & Disc in TP NE 45.85', Spike & Disc in TP SE 30.05'.

11-20-1955 County Highway Department, (CHD Book No. 220, Page 2), P.I. Sta. 26+23.5. RPs - Disc in fence post NE 49.65', Disc in PP SE 53.5'.

10-29-1973 Roger Brand, County Surveyor, dug and found 3-sided boulder 20" long and 10" thick down 3.5'. Set Cast Iron Monument over 1-1/4"x16" pipe over stone. RPs - Concrete nail in north side PP #40162 WSW 55.35', Concrete nail in NW side PP #40161 NE 56.0', Concrete nail in NE side PP #40934 SE 55.2'.

5-31-1984 County Survey Crew found Cast Iron Monument at surface in good condition.

6-3-1999 County Survey Crew found Cast Iron Monument at surface in good condition. Set 1" square pipe w/cap as reference and referenced corner prior to cold recycling bituminous project. Removed Cast Iron Monument.

8-4-2000 County Survey Crew set 1" square pipe w/cap at surface at 1999 referenced location. The corner falls 1/2' west of centerline of CSAH 3, 2' south of centerline of township road east and in line with fence and pole line east.

2-1-2005 County Survey Crew found 1" square pipe w/cap at surface in good condition. RPs - County Survey Disc in south side PP #40162 WSW 55.35', County Survey Disc in NW side PP #40161 NE 55.98', County Survey Disc in NE side PP SE 54.73'.

7-14-2006 County Survey Crew found 1" square pipe w/cap at surface in good condition and measured its position using GPS.