Certificate of Location of Government Corner

ID#: 651706 **Description:** 1/4 SEC COR 17 18 65 **Date Set:** 9/18/2001 **County:** Olmsted

Section: 17 **Township:** 106N **Range:** 15W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 3 1/2' south of centerline of CSAH 25 and 3 1/2' west of centerline of twp road north
County highway disk in NW side PP #8576 (up 7') NE 62.73'
Bottle cap in W side CP SSE 45.5'
Punch mark in clamp lug E end CMP NE 48.10'
Punch mark in clamp lug W end CMP NW 44.51'
Ref pipe NE 88.39'
This corner is located by GPS measurement

Corner History:

6-1854 Michael Karrick 40.00 set quarter section post. Burr Oak 15 S 47 E 225. Dug trench. History of corner location: W. Fraser set limestone by midway and line in 5-1893. We found limestone (2"x8" top) with a large boulder over it. Limestone is about 4' deep in blacktop road. We left limestone in place and set a 1¼"x19" iron pipe over it with cast iron monu. over pipe with top of monu. flush with surface of road.

6-12-1935 J.Kerr (B.10 P.5) run East line 17, may have used corners on west line.

7-1969 J.Kerr meas from SE 18 (CIM) North set hard nail on random line in center new blacktop came at 2637.15 (R.2636 or near record)

7-18-1969 J.Kerr found 1/16 stone South.

10-1-1970 County Surveyor dug 18" x 30" hole in blacktop and 12" rock base below. Found large boulder 10 x 15 x 16 lying flat on top of limestone with 2" x 8" top quite long 3.5' below top of blacktop road. Set 1 1/4" x 19" galv pipe over limestone with CIM flush with road surface.

11-9-1999 County Surveyor found CIM 2" deep in blacktop in good condition.

6-5-2001 County Surveyor set 1" square pipe w/cap as ref pipe for 2001 overlays. Tied out corner and removed CIM.

9-18-2001 County Surveyor set 1" square pipe w/cap at surface from 2001 overlay tie out.

2-11-2010 County Surveyor found 1" square pipe w/cap at surface in good condition.