Certificate of Location of Government Corner

ID#: 652204 **Description:** 1/4 SEC COR 22 27 65 **Date Set:** 2/25/2000 **County:** Olmsted

Section: 22 **Township:** 106N **Range:** 15W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 2 1/2' east of centerline of CSAH 3 and in line with fences east and west
Top lug nut N end 24" CMP NE 43.5'
County Survey Disk in S side PP #41223 ESE 52.65'
SE block cor. of house SW 182.1'
Ref. pipe E 49.42'
This corner is located by GPS measurement

Corner History:

7-1854 Gov't Notes Michael Karrick, Deputy Surveyor, set quarter post 40.00 chs. West of Section Cor. 22-23-26-27. Made mound with trench pits, charred stake and planted osage orange seeds N.E. and S.W.

3-1878 Thomas Hunter, County Surveyor, (P.331 No.325) found remains of old stake incenter of road in line of fence running west. Set boulder stone 8"x10"x18" in place of stake.

1933 county highway department (B.76 P.2) found stone monument.

1964 county highway department (B.285) found pointed boulder. Left stone in place and set 2"x2" wood hub riser.

1972 County Surveyor dug in area of corner and found that Co. H.D. had subcut for road grading and therefore no chance of old stone still being there.

9-3-1974 County Surveyor set C.I.M. over 5/8" rod in surface Co. Rd.3, 2.3' east of center line. Set this corner by projecting line of S. 1/4 Cor. 27 over Center 27 and on east-west section line. This corner falls very close to average line of fences running east and west.

5-28-1999 County Surveyor found CIM in good shape 3" deep in CR #3, set ref pipe and ties.

2-25-2000 County Surveyor set 1" square pipe w/cap at surface from 1999 tie out.