Certificate of Location of Government Corner

ID#: 652304 **Description:** 1/4 SEC COR 23 26 65 **Date Set:** 8/20/1973 **County:** Olmsted

Section: 23 **Township:** 106N **Range:** 15W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls under E-W fence and 1' west of fence south
Post w/sign 1' west
This corner is located by GPS reference stations "Homes A & B"

Corner History:

1854 Gov't Notes M.G Karrick, Deputy Surveyor West on true line between sections 23 and 26 40.00 chs. Set quarter section post in mound with trench, pits and charred stake. Planted Osage orange seeds N.E. and S.W.

6-1874 Thomas Hunter (P.254 No.254), County Surveyor, found mound with stake remains in center. Set new stake.

6-1887 T. Hunter (P.420 No. 409) found cedar post in mound where fences east, west and south meet.

12-1894 William Fraser (P.562 No.516), County Surveyer, found cedar stake.

8-20-1973 County Surveyor found 1/16 stone west. Ran line and doubled distance east and set a C.I.M. over a 1/2"x30" rod. There are many boulders in the area of the corner around the corner post and found nothing after digging.

10-13-2006 County Surveyor found CIM at surface in good condition.