Certificate of Location of Government Corner

ID#: 701805 **Description:** W SEC COR 18 19 70 **Date Set:** 9/10/1992 **County:** Winona

Section: 18 **Township:** 107N **Range:** 10W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1' east of N-S fence and 8' south of pasture fence west
County Survey Disk in PP #1145 ESE 60.29'
County Survey Disk in W side 12" Cherry NNW 19.57'
Post w/sign 1' east
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes John Ball, Deputy Surveyor North between sections 19 and 24 80.00 chs. set post corner to sections. 13, 18, 19, 24, burr oak S76ºE 87 lks. burr oak N72ºE 101 lks. burr oak S35ºW 75 lks.

10-1896 William Fraser, County Surveyor (page 595, No. 541) Stake gone, but SW bearing tree standing set stake from this. Chained south 39.76 set cedar stake midway and on line S0º 25'W.

5-1900 Robert Fraser, Deputy County Surveyor (Page 679, No. 604) Found cedar stake set by William Fraser, tested stake with bearing tree found it correct.

1923 E.C. Burns used corner, no monument type, chained east to quarter corner 18, 19, 37.18 chs. used corner to set quarter corner south midway and on line.

6-12-1992 Olmsted County Surveyor found 1 1/4" iron shaft with 2" top 36" long. Dug around shaft 12" deep to clay to cover line of E.C. Burns pipe mark found at east quarter corner of section 24, found nothing.

9-10-1992 Olmsted County Surveyor set telspar pipe w/cast iron cap at location of iron shaft found 6-12.

7-21-2009 Olmsted County Surveyor found CIC on telspar pipe down 0.1' in good condition.