Certificate of Location of Government Corner

ID#: 701906 **Description:** W 1/4 SEC COR 19 70 **Date Set:** 9/10/1992 **County:** Winona

Section: 19 **Township:** 107N **Range:** 10W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is down 0.4'
The corner falls on north edge of DNR access road
County Survey Disk in CP to parking area fence E 43.76'
This corner is located by GPS measurement

Corner History:

6-1853 Gov't Notes John Ball, Deputy Surveyor North between sections 19 and 24 40.00 chs. Set quarter section post 10" Burr Oak S20ºE 174 lks. 10" Burr Oak N 7ºW 402 lks.

10-1896 William Fraser, County Surveyor (page 595 No. 541) Could not find corner, so set stake midway and on line between north and south section corners 39.76 chs.

5-1900 Robert Fraser, Deputy County Surveyor (Page 679, No. 604) Found cedar stake in middle of road as set by William Fraser in 1896, left as found. Mr. Drysdale claims he will set a stone by stake later. Set stakes for fencing to section corner north, measure 15 3/4 links short in half mile.

1923 E.C. Burns found stone marked with X.

1924 E.C. Burns set pipe midway and online and witness pipes north and south 33'.

6-9-1992 Olmsted County Surveyor found 1 1/2" pipe up 1 foot leaning NE, 33' south of corner.

8-3-1992 Olmsted County Surveyor dug and found rust mark of pipe set by Burns in 1924.

9-10-1992 Olmsted County Surveyor set telspar pipe with cast iron cap at rust mark location found 8-3-1992.

7-20-2009 County survey crew found cast iron cap on telspar pipe in good condition.

12-30-2010 County survey crew found cast iron cap on telspar pipe in good condition.