# Certificate of Location of Government Corner

**ID#:** 710105 **Description:** SEC COR 1 2 11 12 71 **Date Set:** 6/23/1977 **County:** Olmsted

**Section:** 01 **Township:** 107N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

**Reference Ties:**

The corner falls on a very steep hillside sloping down to the NW
Huge stone 3' x 4' by 2' thick above ground (magnetic Brg.) N3°W 84.2' (slope)
Center of 15" Black Oak with probable old blaze (magnetic brg.) N 84.2 (slope)
County Survey Disk in W side blazed 12" Black Oak (magnetic Brg.) N50°E 12.46'
County Survey Disk in W side 10" blazed Black Oak (magnetic Brg.) S64°W 19.60'
County Survey Disk in E side blazed 5" Black Oak (magnetic Brg.) S6°E 22.30'
This corner is located by GPS measurement

**Corner History:**

10-1853 Gov't Notes William A. Jones, Deputy Surveyor North between sections 11 and 12 80.00 chs. Set section post corner to sections 1,2,11,12 Black Oak 10 in. diam. N30°W 83 lks. Black Oak 9 in. diam. N20°E 93 lks. Black Oak 10 in. diam. S40°E 15 lks. Bur Oak 10 in. diam. S50°W 86 lks.

10&11, 1900 William Fraser (P. 692-8 No. 615 and Field Book 9 P.61-67), County Surveyor, found the stub of the old stake in the center of a pile of rocks. Tested the corner with the S.E.
and N.W. bearing trees standing and the stump of the S.W. bearing tree. Drove a new Oak stake in place of the old stake.

6-23-1977 County Surveyor found a ring of stones (but no stake) and the S.E. Gov't bearing tree which proved the stones correct. The bearing tree is now 22" diameter and broken off about 10' above the ground but the blaze is plain. Drove a Cast Iron Cap on a square pipe as the corner in the center of the stones.

1-12-2010 County survey crew found cast iron cap on telspar pipe up 0.5' in good condition.