Certificate of Location of Government Corner

ID#: 710204 **Description:** 1/4 SEC COR 2 11 71 **Date Set:** 6/23/1977 **County:** Olmsted

Section: 02 **Township:** 107N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 15' south of E-W fence and 30' west of short fence south
County Survey Disk in SE side blazed 8" Red Oak NNE 29.72'
County Survey Disk in SE side blazed 12" Hackberry NE 37.40'
This corner is located by GPS reference stations "710204 A & B"

Corner History:

10-1853 Gov't Notes William A. Jones, Deputy Surveyor West on true line between sections 2 and 11. 32.08 chs. Spring Head. Brooks Course N and ascend a bluff - 180 ft. 40.04 chs. On top of bluff and leave timber N & S. Set quarter section corner in mound of earth and sod. Deposited charcoal. Made trench and pits and planted osage orange seed N & S 80.08 chs. To section corner.

10&11-1900 William Fraser (P. 692-8 No. 615 and Field Book 9 P. 61-69), could not find the corner. Set an 8" x 8" x 36" stone midway and on line between the section corners as the corner.

6-23-1977 County Surveyor found the remaining 14" of Fraser's 8" x 8" stone 12" deep in a cultivated field. Drove a Cast Iron Cap on a square pipe as the corner and set the stone on the South side.

1-13-2010 County Surveyor found cast iron cap on telspar pipe down 0.9' in good condition.